



Drainage System Inspection Report

Drainage System: County Ditch 60
 Inspection Date: 2025-07-18
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4: X
 District 5:

Type of Inspection:

By Foot:
 ATV:
 Pickup: X
 Drone: X

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 60

Noxious Weeds Present

There were no noxious weeds found in County Ditch 60

Trees Present

There were no trees found in County Ditch 60



Drainage System Repair Report - 2025

Drainage System: County Ditch 60

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
24-494	Closed	Troy	8	Beaver Dam	2 dams Mark Revier is trapping	\$965.00
Final Repair Cost						\$965.00

Requested Repairs (Lines)


Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection









Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
20-311	Closed	Troy	8	Blockage	Water backed up in open channel. Outlet pipe 3/4 full.	
Final Repair Cost						

Total Ditch Repair Cost:

\$965.00



© OpenStreetMap (and) contributors, CC-BY

Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments



Drainage System Inspection Report

Drainage System: County Ditch 63
 Inspection Date: 2025-06-09
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3: X
 District 4: X
 District 5:

Type of Inspection:

By Foot:
 ATV: X
 Pickup:
 Drone: X

Comments:

Required Repairs

Repair Number	Request Date	Repair Type	Comments	Township	Section
25-076	2025-07-15	Bank Slide		Kingman	21
25-075	2025-07-15	Blockage	North box culvert has dirt blockage	Kingman	35
25-074	2025-06-17	Multiple Bank Slides	Large slides	Bird Island	7
25-075	2025-06-17	Washout		Troy	12
25-071	2025-06-09	Bank Slide		Troy	36
25-072	2025-06-09	Blockage	Island in the channel	Troy	36
25-073	2025-06-09	Bank Slide		Troy	24
25-077	2025-07-18	Tile Line Holes		Kingman	19

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 63

Noxious Weeds Present

The following is made for the Renville County Board of Commissioners pursuant to the provisions of Minnesota State Statutes Section 103E.



Drainage Department

Government Services Center
105 South 5th Street - Suite 319 - Olivia, MN 56277
Office: 320-523-3759 - Fax: 320-523-3755
www.renvillecountymn.com

Parcel Number	Landowner	Created Date
18-00220-00	Mellies Brothers Inc.	2025-12-16

Trees Present

There were no trees found in County Ditch 63



Drainage System Repair Report - 2025

Drainage System: County Ditch 63

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
20-001	Closed	Kingman	19	Tile Line Holes	Repair 2 washouts on county line	\$1,857.43
20-172	Closed	Troy	14	Washout	Ditch bank washout	\$3,792.93
20-303	Closed	Kingman	33	Beaver Dam		\$328.00
20-321	Closed	Kingman	17	Flow Issue	Cleanout - Jacobs	\$6,365.00
21-233	Closed	Troy	24	Tile Line Repair	Camera line and bring tile back to grade.	\$1,000.00
22-201	Closed	Melville	7	Washout	Check washouts in spring and call Vern with what we find	
22-220	Closed	Bird Island	3	Rusted Pipe	30" outlet pipe rusted out	\$3,544.80
22-346	Closed	Winfield	24	Tile Line Holes	Jacobs will fix collapse tile filled with mud.	\$382.50
22-357	Closed	Kingman	29	Fix Crossing		\$1,846.38
22-404	Closed	Kingman	19	Tile Line Repair		\$300.00
22-443	Closed	Bird Island	6	Beaver Dam	Mark will trap	\$800.00
23-203	Closed	Bird Island	10	Rusted Pipe		\$935.48
23-211	Closed	Troy	1	Tile Line Holes		\$1,312.50
23-260	Closed	Troy	10	Flow Issue	Owner thinks there is a problem with tree roots.	
24-211	Closed	Troy	13	Beaver Dam		\$767.50
24-215	Closed	Troy	24	Tile Line Repair	Relay approximately 150ft of 18". Bed in rock.	\$1,481.00
24-221	Closed	Troy	10	Tile Line Holes	Relay tile through the road and relay 10' of 24" surface pipe	\$4,749.00
24-225	Closed	Troy	12	Washout	Rip Rap water way	\$5,918.55
24-254	Closed	Troy	11	Plugged Tile		\$2,262.00
24-436	Closed	Bird Island	2	Washout		\$2,104.73
24-455	Closed	Kingman	33	Beaver Dam		\$1,560.00
24-456	Closed	Kingman	28	Beaver Dam		\$450.00
24-484	Closed	Bird Island	1	Tree Spraying		\$1,785.00

The following is made for the Renville County Board of Commissioners pursuant to the provisions of Minnesota State Statutes Section 103E.



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

24-493	Closed	Troy	25	Beaver Dam	Cody Dale is trapping Ready to be removed Might need a long reach to remove the dam	\$1,025.00
24-497	Closed	Henryville	12	Beaver Dam	Mark Revier is trapping	\$665.00
24-518	Closed	Troy	10	Tile Connection		\$340.00
24-526	Closed	Bird Island	1	Tree Spraying		\$2,805.00
25-332	Awaiting	Bird Island	6	Tile Line Repair	Plow in a tile line for Paul Erickson in the spring next to the main dug in	
Final Repair Cost						\$48,377.80

Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
20-269	Closed	Melville	6	Camera Run	video cam tile line		\$6,000.00
24-804	Closed	Troy	10	Camera Run			\$460.00
25-819	Closed	Bird Island	6	Camera Run	Are there tree roots in the line?	8665.20	\$82,062.33
Final Repair Cost							\$88,522.33

Repairs Collected During Inspection




Drainage Department

Government Services Center
105 South 5th Street - Suite 319 - Olivia, MN 56277
Office: 320-523-3759 - Fax: 320-523-3755
www.renvillecountymn.com









Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
20-121	Closed	Kingman	33	Fix Crossing	Remove	\$6,482.21
20-129	Closed	Troy	14	Bank Slide		
20-121.1	Closed	Kingman	33	Washout		
20-119	Closed	Bird Island	12	Rusted Pipe		\$2,087.20
19-407	Awaiting	Troy	12	Fix Crossing		
19-401	Closed	Kingman	31	Tile Line Repair		\$2,498.14
20-127	Closed	Kingman	16	Rusted Pipe	Jacobs will do during cleanout	
18-025	Closed	Troy	14	Tile Connection		\$38,037.08
20-031	Closed	Troy	14	Tile Line Repair		\$10,020.00
20-094	Closed	Winfield	24	Tile Line Repair		\$365.29
20-055	Closed	Kingman	30	Tile Line Repair		
20-052	Closed	Kingman	30	Tile Line Repair		
17-154	Closed	Bird Island	12	Fix Crossing		
19-126	Closed	Kingman	17	Tile Line Repair	Tile in fall of 2021 Jacobs will do	
25-076	Awaiting	Kingman	21	Bank Slide		
25-075	Awaiting	Kingman	35	Blockage	North box culvert has dirt blockage	
25-074	Awaiting	Bird Island	7	Bank Slide Multi	Large slides	
25-075	Awaiting	Troy	12	Washout		
25-071	Awaiting	Troy	36	Bank Slide		
25-072	Awaiting	Troy	36	Blockage	Island in the channel	
25-073	Awaiting	Troy	24	Bank Slide		
25-077	Invoiced	Kingman	19	Tile Line Holes		
Final Repair Cost						\$59,489.92

Total Ditch Repair Cost:

\$196,390.05



County Ditch 63

Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments



Drainage System Inspection Report

Drainage System: County Ditch 70
 Inspection Date: 2025-07-18
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3: X
 District 4: X
 District 5:

Type of Inspection:

By Foot: X
 ATV:
 Pickup:
 Drone: X

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 70

Noxious Weeds Present

There were no noxious weeds found in County Ditch 70

Trees Present

There were no trees found in County Ditch 70



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Repair Report - 2025

Drainage System: County Ditch 70

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						


Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
Final Repair Cost						

Total Ditch Repair Cost: \$0.00



© OpenStreetMap (and) contributors, CC-BY



County Ditch 70

Repair Status			
	Awaiting		Buffer Noncompliances
	Closed		Noxious Weed Blights
	Invoiced		Tree Maintenance Segments
	Level/Seed		
	Open		



Drainage System Inspection Report

Drainage System: County Ditch 101
 Inspection Date: 2025-07-18
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4: X
 District 5:

Type of Inspection:

By Foot: X
 ATV:
 Pickup:
 Drone: X

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 101

Noxious Weeds Present

There were no noxious weeds found in County Ditch 101

Trees Present

There were no trees found in County Ditch 101



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Repair Report - 2025

Drainage System: County Ditch 101

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
20-067	Closed	Troy	20	Plugged Tile	Jet Tile Line	\$1,085.00
Final Repair Cost						\$1,085.00


Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection









Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
Final Repair Cost						

Total Ditch Repair Cost: \$1,085.00



© OpenStreetMap (and) contributors, CC-BY

County Ditch 101

Repair Status			
	Awaiting		Buffer Noncompliances
	Closed		Noxious Weed Blights
	Invoiced		Tree Maintenance Segments
	Level/Seed		
	Open		



Drainage System Inspection Report

Drainage System: Judicial Ditch 22
 Inspection Date: 2025-07-18
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3: X
 District 4: X
 District 5:

Type of Inspection:

By Foot: X
 ATV:
 Pickup:
 Drone: X

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch Judicial Ditch 22

Noxious Weeds Present

There were no noxious weeds found in Judicial Ditch 22

Trees Present

There were no trees found in Judicial Ditch 22



Drainage System Repair Report - 2025

Drainage System: Judicial Ditch 22

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						


Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							









Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
Final Repair Cost						

Total Ditch Repair Cost: \$0.00



Judicial Ditch 22

Repair Status			
	Awaiting		Buffer Noncompliances
	Closed		Noxious Weed Blights
	Invoiced		Tree Maintenance Segments
	Level/Seed		
	Open		