



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Inspection Report

Drainage System: County Ditch 17A
 Inspection Date: 2025-05-27
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

- District 1:
- District 2:
- District 3:
- District 4:
- District 5: X

Type of Inspection:

- By Foot:
- ATV: X
- Pickup:
- Drone:

Comments:

Required Repairs

Repair Number	Request Date	Repair Type	Comments	Township	Section
25-052	2025-05-27	Bank Slide	Large bank slide	Crooks	25
25-051	2025-05-27	Bank Slide		Crooks	25
25-053	2025-05-27	Bank Slide		Crooks	25
25-050	2025-05-27	Washout	Washout on the corner	Crooks	25
25-057	2025-05-27	Rusted Pipe		Crooks	12
25-049	2025-05-27	Beaver Dam	Beaver dam in culvert	Crooks	36
25-048	2025-05-27	Bank Slide		Crooks	36
25-058	2025-05-27	Fix Crossing	End pipes are separated and sucking dirt (cone pipes)	Crooks	12
25-055	2025-05-27	Bank Slide	Small slide	Crooks	26
25-059	2025-05-27	Bank Slide		Crooks	12
25-054	2025-05-27	Fix Crossing	Steel arch crossing is squatting and washing out	Crooks	26
25-062	2025-06-04	Blockage	Look into cleaning half mile going to the east	Crooks	15
25-060	2025-06-04	Fix Crossing	48" crossing pipe are separated	Crooks	11

Completed Repairs

The following is made for the Renville County Board of Commissioners pursuant to the provisions of Minnesota State Statutes Section 103E.



Drainage Department

Government Services Center
105 South 5th Street - Suite 319 - Olivia, MN 56277
Office: 320-523-3759 - Fax: 320-523-3755
www.renvillecountymn.com

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 17A

Noxious Weeds Present

Parcel Number	Landowner	Created Date
09-00510-00	Russell & Luann Nere	2025-06-04
09-00900-00	Hanson Properties	2025-06-04

Trees Present

There were no trees found in County Ditch 17A



Drainage System Repair Report - 2025

Drainage System: County Ditch 17A

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
20-040	Closed	Crooks	22	Washout		\$2,263.80
20-081	Closed	Crooks	22	Reseed	Redetermination seeding	\$5,320.00
20-205	Closed	Crooks	23	Fix Crossing	Replace crossing	\$20,773.09
22-260	Closed	Crooks	23	Washout		\$2,788.55
22-261	Closed	Crooks	15	Washout		\$1,928.00
22-262	Closed	Crooks	15	Washout		\$2,344.00
22-263	Closed	Crooks	15	Washout		\$184.00
22-264	Closed	Crooks	10	Washout		\$184.00
22-269	Closed	Crooks	22	Washout		\$1,312.90
22-270	Closed	Crooks	36	Washout		\$1,574.77
22-287	Closed	Crooks	36	Washout		\$3,707.14
22-289	Closed	Crooks	26	Washout		\$5,090.54
22-331	Closed	Crooks	36	Washout		\$8,083.92
22-332	Closed	Crooks	25	Washout		\$4,664.15
22-333	Closed	Crooks	25	Washout		\$2,735.00
22-334	Closed	Crooks	25	Washout		\$432.25
22-335	Closed	Crooks	25	Washout		\$7,757.83
22-336	Closed	Crooks	25	Washout		\$138.50
22-337	Closed	Crooks	25	Washout		\$9,644.53
22-417	Closed	Crooks	23	Rusted Pipe	457ft from pipeline. Locate called in 10-13-2022	\$1,882.20
22-442	Closed	Crooks	36	Beaver Dam	Mark will trap	
24-219	Level/Se ed	Crooks	22	Fix Crossing	Add 2 pipe from the crossing we are removing	\$9,983.28
24-471	Closed	Crooks	36	Beaver Dam		\$1,040.00
Final Repair Cost						\$93,832.45



Drainage Department

Government Services Center
105 South 5th Street - Suite 319 - Olivia, MN 56277
Office: 320-523-3759 - Fax: 320-523-3755
www.renvillecountymn.com

Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
25-052	Level/Seed	Crooks	25	Bank Slide	Large bank slide	
25-051	Level/Seed	Crooks	25	Bank Slide		
25-053	Level/Seed	Crooks	25	Bank Slide		\$11,176.26
25-050	Level/Seed	Crooks	25	Washout	Washout on the corner	\$1,465.65
25-048	Level/Seed	Crooks	36	Bank Slide		\$2,664.83
25-058	Level/Seed	Crooks	12	Fix Crossing	End pipes are separated and sucking dirt (cone pipes)	
25-055	Level/Seed	Crooks	26	Bank Slide	Small slide	\$2,975.20
25-059	Level/Seed	Crooks	12	Bank Slide		\$4,259.28
25-062	Awaiting	Crooks	15	Blockage	Look into cleaning half mile going to the east	
25-060	Level/Seed	Crooks	11	Fix Crossing	48" crossing pipe are separated	\$10,050.00
Final Repair Cost						\$32,591.22

Total Ditch Repair Cost:

\$126,423.67



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Inspection Report

Drainage System: County Ditch 31
 Inspection Date: 2025-06-04
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

- District 1:
- District 2:
- District 3: X
- District 4:
- District 5: X

Type of Inspection:

- By Foot:
- ATV: X
- Pickup:
- Drone: X

Comments:

Required Repairs

Repair Number	Request Date	Repair Type	Comments	Township	Section
25-065	2025-06-04	Rusted Pipe		Crooks	24
25-067	2025-06-04	Washout		Winfield	19
25-064	2025-06-04	Bank Slide		Crooks	25
25-069	2025-06-05	Bank Slide		Winfield	7
25-066	2025-06-04	Bank Slide		Winfield	19
25-063	2025-06-04	Washout		Crooks	25
25-070	2025-06-05	Washout		Winfield	7

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 31

Noxious Weeds Present

There were no noxious weeds found in County Ditch 31

The following is made for the Renville County Board of Commissioners pursuant to the provisions of Minnesota State Statutes Section 103E.



Drainage Department

Government Services Center
105 South 5th Street - Suite 319 - Olivia, MN 56277
Office: 320-523-3759 - Fax: 320-523-3755
www.renvillecountymn.com

Trees Present

There were no trees found in County Ditch 31



Drainage System Repair Report - 2025

Drainage System: County Ditch 31

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
19-437	Closed	Winfield	20	Fix Crossing	clean both sides of crossing	\$1,000.00
20-037	Closed	Crooks	24	Rusted Pipe	Outlet covered by cleanout	\$1,120.00
20-043	Closed	Winfield	18	Rusted Pipe	2 county pipes rusted out	\$2,820.78
20-082	Closed	Winfield	19	Reseed	Redetermination seeding	\$1,290.00
	Closed	Crooks	25	Fix Crossing	Check condition of crossing in the spring, highway is replacing the road crossing	
21-261	Closed	Winfield	22	Beaver Dam	Cody Dale Trapping	\$645.00
22-212	Closed	Crooks	24	Drop Pipe Needed	Water overtopped ditch	\$1,338.50
22-213	Closed	Crooks	25	Washout	Corner washout past existing rock	\$4,684.10
22-288	Closed	Crooks	25	Bank Slide		\$138.50
22-350	Closed	Crooks	24	Washout		\$3,427.47
23-205	Awaiting	Winfield	17	Blockage	Dig up road	
24-462	Closed	Winfield	31	Beaver Dam	3 dams Ready to be removed	\$885.00
Final Repair Cost						\$17,349.35

Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection




Drainage Department









Government Services Center
105 South 5th Street - Suite 319 - Olivia, MN 56277
Office: 320-523-3759 - Fax: 320-523-3755
www.renvillecountymn.com

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
25-067	Level/Seed	Winfield	19	Washout		
25-064	Level/Seed	Crooks	25	Bank Slide		
25-069	Level/Seed	Winfield	7	Bank Slide		\$1,562.08
25-066	Level/Seed	Winfield	19	Bank Slide		\$2,237.48
25-063	Level/Seed	Crooks	25	Washout		\$2,239.68
25-070	Closed	Winfield	7	Washout		
Final Repair Cost						\$6,039.24

Total Ditch Repair Cost:

\$23,388.59



Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Inspection Report

Drainage System: County Ditch 37C
 Inspection Date: 2025-05-14
 Next Inspection Date: 2025
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot:
 ATV: X
 Pickup:
 Drone: X

Comments:

Required Repairs

Repair Number	Request Date	Repair Type	Comments	Township	Section
25-043	2025-05-14	Blockage	Blockage in front of west box culvert	Emmet	12
25-044	2025-05-15	Washout	Small washout	Crooks	33

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 37C

Noxious Weeds Present

Parcel Number	Landowner	Created Date
09-01490-00	David Henneberry	2025-05-15

Trees Present

There were no trees found in County Ditch 37C

The following is made for the Renville County Board of Commissioners pursuant to the provisions of Minnesota State Statutes Section 103E.



Drainage System Repair Report - 2025

Drainage System: County Ditch 37C

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
17-254	Closed	Crooks	33	Flow Issue	Islands to pull out proposed cleanout	\$82,558.48
20-151	Closed	Emmet	2	Reseed	Haul out spoil	\$13,787.93
21-239	Closed	Emmet	12	Reseed		\$1,819.00
21-258	Closed	Crooks	29	Fix Crossing		\$2,100.00
21-292	Closed	Crooks	29	Rusted Pipe	Jacobs hit a private pipe during the cleanout	
22-444	Closed	Emmet	2	Beaver Dam	beaver dam under the tracks. Mark will trap after deer hunting Nov 14	
23-250	Closed	Crooks	34	Fix Crossing	Repair ditch crossing and tie	\$3,710.75
Final Repair Cost						\$103,976.16

Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							









Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
20-304	Closed	Crooks	33	Beaver Dam	Cody Dale Trapping	
25-043	Open	Emmet	12	Blockage	Blockage in front of west box culvert	
25-044	Level/Seed	Crooks	33	Washout	Small washout	\$1,049.85
Final Repair Cost						\$1,049.85

Total Ditch Repair Cost:

\$105,026.01



Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments



Drainage System Inspection Report

Drainage System: County Ditch 52
 Inspection Date: 2025-05-14
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot: X
 ATV:
 Pickup:
 Drone: X

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 52

Noxious Weeds Present

There were no noxious weeds found in County Ditch 52

Trees Present

There were no trees found in County Ditch 52



Drainage System Repair Report - 2025

Drainage System: County Ditch 52

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
	Closed	Emmet	29		Reseed staging area for 52 Project	\$243.75
24-263	Closed	Emmet	28	Tile Connection	6" line did not get tied into new main	\$728.98
Final Repair Cost						\$972.73

Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							









Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
Final Repair Cost						

Total Ditch Repair Cost:

\$972.73



Repair Status			
	Awaiting		Buffer Noncompliances
	Closed		Noxious Weed Blights
	Invoiced		Tree Maintenance Segments
	Level/Seed		
	Open		



Drainage System Inspection Report

Drainage System: County Ditch 71
 Inspection Date: 2025-05-09
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot: X
 ATV: X
 Pickup:
 Drone:

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 71

Noxious Weeds Present

There were no noxious weeds found in County Ditch 71

Trees Present

There were no trees found in County Ditch 71



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Repair Report - 2025

Drainage System: County Ditch 71

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						

Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							









Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
Final Repair Cost						

Total Ditch Repair Cost: \$0.00



© OpenStreetMap (and) contributors, CC-BY

Repair Status			
	Awaiting		Buffer Noncompliances
	Closed		Noxious Weed Blights
	Invoiced		Tree Maintenance Segments
	Level/Seed		
	Open		



Drainage System Inspection Report

Drainage System: County Ditch 72
 Inspection Date: 2025-05-05
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot: X
 ATV:
 Pickup:
 Drone:

Comments: Clay tile on Br-Main are breaking down at the outlet. Look into account building to address this in the future

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 72

Noxious Weeds Present

There were no noxious weeds found in County Ditch 72

Trees Present

There were no trees found in County Ditch 72



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Repair Report - 2025

Drainage System: County Ditch 72

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						


Requested Repairs (Lines)









Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
Final Repair Cost						

Total Ditch Repair Cost: \$0.00



Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments



Drainage System Inspection Report

Drainage System: County Ditch 75
 Inspection Date: 2025-05-05
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot: X
 ATV: X
 Pickup:
 Drone:

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 75

Noxious Weeds Present

There were no noxious weeds found in County Ditch 75

Trees Present

There were no trees found in County Ditch 75



Drainage System Repair Report - 2025

Drainage System: County Ditch 75

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
20-123	Closed	Wang	24	Tile Line Repair	Tile reroute Vreemans will do	\$14,639.46
20-058	Closed	Wang	23	Tile Line Holes	Tile washout with big hole	\$1,500.00
20-282	Closed	Wang	28	Tree Spraying		\$360.00
Final Repair Cost						\$16,499.46

Requested Repairs (Lines)


Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							







Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
Final Repair Cost						

Total Ditch Repair Cost:

\$16,499.46



Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments



Drainage System Inspection Report

Drainage System: County Ditch 77
 Inspection Date: 2025-05-05
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot:
 ATV: X
 Pickup:
 Drone:

Comments: Outlet being repaired with lift pumps and a small stretch of completed in 2024

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 77

Noxious Weeds Present

There were no noxious weeds found in County Ditch 77

Trees Present

There were no trees found in County Ditch 77



Drainage System Repair Report - 2025

Drainage System: County Ditch 77

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
20-059	Closed	Hawk Creek	15	Beaver Dam	Remove beaver dam	\$500.00
21-288	Closed	Hawk Creek	11	Flow Issue		
22-377	Closed	Hawk Creek	3	Washout	Intake washed out in west road ditch of CR 10, needs half load of fill.	\$494.56
24-204	Closed	Hawk Creek	14	Blockage	CD 77 Imp/Repair	\$25,880.00
Final Repair Cost						\$26,874.56

Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection









Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
24-204	Closed	Hawk Creek	14	Blockage	See exhibit A	\$25,880.00
Final Repair Cost						\$25,880.00

Total Ditch Repair Cost:

\$52,754.56



County Ditch 77

Repair Status			
	Awaiting		Buffer Noncompliances
	Closed		Noxious Weed Blights
	Invoiced		Tree Maintenance Segments
	Level/Seed		
	Open		



Drainage System Inspection Report

Drainage System: County Ditch 83
 Inspection Date: 2025-05-13
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot:
 ATV: X
 Pickup:
 Drone:

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 83

Noxious Weeds Present

There were no noxious weeds found in County Ditch 83

Trees Present

There were no trees found in County Ditch 83



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Repair Report - 2025

Drainage System: County Ditch 83

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						

Requested Repairs (Lines)









Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
Final Repair Cost						

Total Ditch Repair Cost: \$0.00



Repair Status			
	Awaiting		Buffer Noncompliances
	Closed		Noxious Weed Blights
	Invoiced		Tree Maintenance Segments
	Level/Seed		
	Open		



Drainage System Inspection Report

Drainage System: County Ditch 84
 Inspection Date: 2025-05-13
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot: X
 ATV: X
 Pickup:
 Drone:

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 84

Noxious Weeds Present

There were no noxious weeds found in County Ditch 84

Trees Present

There were no trees found in County Ditch 84



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Repair Report - 2025

Drainage System: County Ditch 84

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						


Requested Repairs (Lines)









Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
Final Repair Cost						

Total Ditch Repair Cost: \$0.00



Repair Status			
	Awaiting		Buffer Noncompliances
	Closed		Noxious Weed Blights
	Invoiced		Tree Maintenance Segments
	Level/Seed		
	Open		



Drainage System Inspection Report

Drainage System: County Ditch 86
 Inspection Date: 2025-05-13
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot:
 ATV: X
 Pickup:
 Drone: X

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 86

Noxious Weeds Present

There were no noxious weeds found in County Ditch 86

Trees Present

There were no trees found in County Ditch 86



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Repair Report - 2025

Drainage System: County Ditch 86

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						


Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							









Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
Final Repair Cost						

Total Ditch Repair Cost: \$0.00



County Ditch 86

Repair Status			
	Awaiting		Buffer Noncompliances
	Closed		Noxious Weed Blights
	Invoiced		Tree Maintenance Segments
	Level/Seed		
	Open		



Drainage System Inspection Report

Drainage System: County Ditch 88
 Inspection Date: 2025-05-13
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot: X
 ATV: X
 Pickup:
 Drone:

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 88

Noxious Weeds Present

There were no noxious weeds found in County Ditch 88

Trees Present

There were no trees found in County Ditch 88



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Repair Report - 2025

Drainage System: County Ditch 88

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						

Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
Final Repair Cost						

Total Ditch Repair Cost: \$0.00



© OpenStreetMap (and) contributors, CC-BY

County Ditch 88

Repair Status			
	Awaiting		Buffer Noncompliances
	Closed		Noxious Weed Blights
	Invoiced		Tree Maintenance Segments
	Level/Seed		
	Open		



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Inspection Report

Drainage System: County Ditch 102
 Inspection Date: 2025-05-09
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot:
 ATV: X
 Pickup:
 Drone:

Comments:

Required Repairs

Repair Number	Request Date	Repair Type	Comments	Township	Section
25-024	2025-05-09	Drop Pipe Needed		Crooks	30
25-022	2025-05-09	Multiple Washouts	One bank slide and a rock waterway needed	Crooks	30
25-023	2025-05-09	Bank Slide	Corn	Crooks	30

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 102

Noxious Weeds Present

There were no noxious weeds found in County Ditch 102

Trees Present

There were no trees found in County Ditch 102

The following is made for the Renville County Board of Commissioners pursuant to the provisions of Minnesota State Statutes Section 103E.



Drainage Department

Government Services Center
105 South 5th Street - Suite 319 - Olivia, MN 56277
Office: 320-523-3759 - Fax: 320-523-3755
www.renvillecountymn.com

Drainage System Repair Report - 2025

Drainage System: County Ditch 102

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						

Requested Repairs (Lines)


Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
21-810	Closed	Crooks	30	Flow Issue			\$965.00
Final Repair Cost							\$965.00









Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
20-163	Closed	Crooks	30	Bank Slide	Fall	\$748.75
25-024	Level/Seed	Crooks	30	Drop Pipe Needed		
25-022	Level/Seed	Crooks	30	Washout Multi	One bank slide and a rock waterway needed	\$4,954.85
25-023	Level/Seed	Crooks	30	Bank Slide	Corn	\$696.15
Final Repair Cost						\$6,399.75

Total Ditch Repair Cost:

\$7,364.75



Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments



Drainage System Inspection Report

Drainage System: County Ditch 104
 Inspection Date: 2025-05-08
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot:
 ATV: X
 Pickup:
 Drone:

Comments:

Required Repairs

Repair Number	Request Date	Repair Type	Comments	Township	Section
25-004	2025-05-08	Rock Needed	Build a rock waterway Corn	Sacred Heart North	18
25-005	2025-05-08	Drop Pipe Needed	Old surface pipe washed out	Sacred Heart North	18
25-002	2025-05-08	Bank Slide		Hawk Creek	24
25-003	2025-05-08	Fix Crossing	4 pipe 72" separating and sucking dirt	Sacred Heart North	18
25-006	2025-05-08	Fix Crossing	4 x 72" pipe need to be relayed and tied	Sacred Heart North	18

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 104

Noxious Weeds Present

There were no noxious weeds found in County Ditch 104

The following is made for the Renville County Board of Commissioners pursuant to the provisions of Minnesota State Statutes Section 103E.



Renville
COUNTY
Service · Stewardship · Shared Responsibility

Drainage Department

Government Services Center
105 South 5th Street - Suite 319 - Olivia, MN 56277
Office: 320-523-3759 - Fax: 320-523-3755
www.renvillecountymn.com

Trees Present

There were no trees found in County Ditch 104



Drainage System Repair Report - 2025

Drainage System: County Ditch 104

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
22-342	Closed	Sacred Heart North	18	Washout		\$704.00
22-344	Closed	Sacred Heart North	7	Washout		\$4,105.27
23-257	Closed	Hawk Creek	13	Rusted Pipe	Marlo Sanders will invoice us for a private outlet pipe.	\$393.94
Final Repair Cost						\$5,203.21

Requested Repairs (Lines)


Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
23-807	Closed	Sacred Heart North	7	Reseed	Reseed Buffer		\$831.00
Final Repair Cost							\$831.00

Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
25-004	Open	Sacred Heart North	18	Rock Needed	Build a rock waterway Corn	
25-005	Open	Sacred Heart North	18	Drop Pipe Needed	Old surface pipe washed out	
25-002	Level/Seed	Hawk Creek	24	Bank Slide		\$3,181.63
25-003	Open	Sacred Heart North	18	Fix Crossing	4 pipe 72" separating and sucking dirt	\$379.20
25-006	Open	Sacred Heart North	18	Fix Crossing	4 x 72" pipe need to be relayed and tied	\$379.20
Final Repair Cost						\$3,940.03

Total Ditch Repair Cost:

\$9,974.24



County Ditch 104

Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments



Drainage System Inspection Report

Drainage System: County Ditch 116
 Inspection Date: 2025-05-08
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot:
 ATV: X
 Pickup:
 Drone:

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 116

Noxious Weeds Present

There were no noxious weeds found in County Ditch 116

Trees Present

There were no trees found in County Ditch 116



Drainage System Repair Report - 2025

Drainage System: County Ditch 116

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
20-167	Closed	Ericson	32	Flow Issue	Look into cleanout in the fall	\$534.38
20-285	Closed	Ericson	29	Tree Spraying		\$240.00
21-245	Closed	Ericson	32	Reseed	Redetermination seeding	\$595.00
22-341	Closed	Ericson	32	Washout		\$1,527.36
Final Repair Cost						\$2,896.74

Requested Repairs (Lines)


Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection









Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
20-166	Closed	Ericson	32	Bank Slide Multi		
20-167	Closed	Ericson	29	Flow Issue	Looking into clean out	\$62,813.78
Final Repair Cost						\$62,813.78

Total Ditch Repair Cost:

\$65,710.52



County Ditch 116

Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments



Drainage System Inspection Report

Drainage System: County Ditch 119
Inspection Date: 2025-05-08
Next Inspection Date: 2025
Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
District 2:
District 3:
District 4:
District 5: X

Type of Inspection:

By Foot: X
ATV: X
Pickup:
Drone:

Comments:

Required Repairs

Repair Number	Request Date	Repair Type	Comments	Township	Section
25-017	2025-05-08	Blockage	Possibly need to clean this stretch	Sacred Heart North	8
25-013	2025-05-08	Washout	Bigger washout. Will need a larger excavator	Sacred Heart North	9
25-011	2025-05-08	Bank Slide		Sacred Heart North	16
25-012	2025-05-08	Bank Slide	Small slide	Sacred Heart North	16
25-016	2025-05-08	Bank Slide	Beans	Sacred Heart North	17
25-021	2025-05-08	Washout	Smaller washout	Ericson	27
25-008	2025-05-08	Drop Pipe Needed	Drop is there, the joints are washing out	Sacred Heart North	29
25-010	2025-05-08	Rock Needed	Fill in a waterway for surface water	Sacred Heart North	20
25-018	2025-05-08	Bank Slide	Large slide. Corn	Sacred Heart North	17
25-015	2025-05-08	Rock Needed	Rock around private outlet	Sacred Heart North	16
25-019	2025-05-08	Rusted Pipe		Ericson	33
25-020	2025-05-08	Rusted Pipe	Outlet is washed out	Ericson	27



Drainage Department

Government Services Center
105 South 5th Street - Suite 319 - Olivia, MN 56277
Office: 320-523-3759 - Fax: 320-523-3755
www.renvillecountymn.com

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 119

Noxious Weeds Present

There were no noxious weeds found in County Ditch 119

Trees Present

Parcel Number	Landowner	Created Date
23-03230-00	Eric Hendrickson	2025-05-08



Drainage System Repair Report - 2025

Drainage System: County Ditch 119

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
20-286	Closed	Ericson	28	Tree Spraying		\$480.00
22-317	Closed	Sacred Heart North	29	Washout		\$1,413.12
22-318	Closed	Sacred Heart North	29	Washout		\$3,211.60
22-323	Closed	Sacred Heart North	9	Washout		\$6,418.50
22-324	Closed	Sacred Heart North	9	Washout		\$5,549.45
22-325	Closed	Ericson	32	Washout		
22-326	Closed	Ericson	33	Washout		\$3,459.28
22-327	Closed	Ericson	33	Washout		\$5,028.69
22-328	Closed	Ericson	33	Washout		\$1,864.00
22-329	Closed	Ericson	28	Washout		\$860.71
22-330	Closed	Ericson	28	Washout		\$862.54
24-472	Closed	Sacred Heart North	16	Beaver Dam	Ready to be removed	\$795.00
25-227	Invoiced	Sacred Heart North	32	Beaver Dam		
25-318	Level/Sealed	Sacred Heart North	29	Washout Multi	3 bank slides 2,3,2 loads	\$8,122.25
Final Repair Cost						\$38,065.14

Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection

The following is made for the Renville County Board of Commissioners pursuant to the provisions of Minnesota State Statutes Section 103E.




Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com




Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
20-295	Closed	Sacred Heart North	29	Washout	Washout around culvert face	
25-013	Level/Seed	Sacred Heart North	9	Washout	Bigger washout. Will need a larger excavator	\$4,208.00
25-011	Level/Seed	Sacred Heart North	16	Bank Slide		
25-012	Level/Seed	Sacred Heart North	16	Bank Slide	Small slide	
25-016	Level/Seed	Sacred Heart North	17	Bank Slide	Beans	\$803.75
25-021	Level/Seed	Ericson	27	Washout	Smaller washout	\$4,439.73
25-008	Level/Seed	Sacred Heart North	29	Drop Pipe Needed	Drop is there, the joints are washing out	
25-010	Level/Seed	Sacred Heart North	20	Rock Needed	Fill in a waterway for surface water	\$840.00
25-018	Level/Seed	Sacred Heart North	17	Bank Slide	Large slide. Corn	\$4,935.40
25-015	Level/Seed	Sacred Heart North	16	Rock Needed	Rock around private outlet	\$5,791.75
Final Repair Cost						\$21,018.63

Total Ditch Repair Cost:

\$59,083.77



County Ditch 119

Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments



Drainage System Inspection Report

Drainage System: County Ditch 122
 Inspection Date: 2025-05-14
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot: X
 ATV:
 Pickup:
 Drone:

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 122

Noxious Weeds Present

There were no noxious weeds found in County Ditch 122

Trees Present

There were no trees found in County Ditch 122



Drainage System Repair Report - 2025

Drainage System: County Ditch 122

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
24-519	Closed	Sacred Heart South	9	Washout		
24-529	Closed	Sacred Heart South	9	Tile Line Repair		\$1,123.00
Final Repair Cost						\$1,123.00

Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
Final Repair Cost						

Total Ditch Repair Cost:

\$1,123.00



© OpenStreetMap (and) contributors, CC-BY

Repair Status			
	Awaiting		Buffer Noncompliances
	Closed		Noxious Weed Blights
	Invoiced		Tree Maintenance Segments
	Level/Seed		
	Open		



Drainage Department

Drainage System Inspection Report

Drainage System: County Ditch 123
 Inspection Date: 2025-05-08
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot:
 ATV: X
 Pickup:
 Drone:

Comments:

Required Repairs

Repair Number	Request Date	Repair Type	Comments	Township	Section
25-007	2025-05-08	Multiple Washouts	Couple of smaller washouts. About 5 loads of rip rap	Sacred Heart North	31

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 123

Noxious Weeds Present

There were no noxious weeds found in County Ditch 123

Trees Present

There were no trees found in County Ditch 123



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Repair Report - 2025

Drainage System: County Ditch 123

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						


Requested Repairs (Lines)









Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
25-007	Level/Seed	Sacred Heart North	31	Washout Multi	Couple of smaller washouts. About 5 loads of rip rap	\$3,599.73
Final Repair Cost						\$3,599.73

Total Ditch Repair Cost: \$3,599.73



Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments



Drainage System Inspection Report

Drainage System: County Ditch 135
 Inspection Date: 2025-05-09
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot: X
 ATV: X
 Pickup:
 Drone:

Comments: Possibly televise to check for tree roots

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 135

Noxious Weeds Present

There were no noxious weeds found in County Ditch 135

Trees Present

There were no trees found in County Ditch 135



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Repair Report - 2025

Drainage System: County Ditch 135

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						

Requested Repairs (Lines)









Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
20-080	Closed	Sacred Heart North	12	Camera Run	Trees over line	\$1,800.00
Final Repair Cost						\$1,800.00

Total Ditch Repair Cost: \$1,800.00



Repair Status			
	Awaiting		Buffer Noncompliances
	Closed		Noxious Weed Blights
	Invoiced		Tree Maintenance Segments
	Level/Seed		
	Open		



Drainage System Inspection Report

Drainage System: County Ditch 139
 Inspection Date: 2025-05-08
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot: X
 ATV: X
 Pickup:
 Drone:

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch County Ditch 139

Noxious Weeds Present

There were no noxious weeds found in County Ditch 139

Trees Present

There were no trees found in County Ditch 139



Drainage System Repair Report - 2025

Drainage System: County Ditch 139

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
20-035	Closed	Ericson	21	Washout		\$6,320.69
20-284	Closed	Ericson	21	Tree Spraying		\$2,160.00
22-340	Closed	Ericson	21	Washout		\$4,732.96
Final Repair Cost						\$13,213.65

Requested Repairs (Lines)









Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
20-021	Closed	Ericson	21	Flow Issue	Clean out scheduled.	\$24,580.00
Final Repair Cost						\$24,580.00

Total Ditch Repair Cost: \$37,793.65



Repair Status	
 Awaiting	 Buffer Noncompliances
 Closed	 Noxious Weed Blights
 Invoiced	 Tree Maintenance Segments
 Level/Seed	
 Open	



Drainage Department

Government Services Center
105 South 5th Street - Suite 319 - Olivia, MN 56277
Office: 320-523-3759 - Fax: 320-523-3755
www.renvillecountymn.com

Drainage System Inspection Report

Drainage System: Judicial Ditch 1
Inspection Date: 2025-05-14
Next Inspection Date: 2030
Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
District 2:
District 3:
District 4:
District 5: X

Type of Inspection:

By Foot:
ATV: X
Pickup:
Drone: X

Comments: Look into cleanout on bottom end

Required Repairs

Repair Number	Request Date	Repair Type	Comments	Township	Section
25-035	2025-05-14	Tile Line Repair	Tile washout	Ericson	3
25-034	2025-05-14	Rock Needed	Needs rock for a waterway	Ericson	3

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch Judicial Ditch 1

Noxious Weeds Present

Parcel Number	Landowner	Created Date
11-00610-00	Schrauth/Darlene	2025-05-14

Trees Present



Renville
COUNTY
Service · Stewardship · Shared Responsibility

Drainage Department

Government Services Center
105 South 5th Street - Suite 319 - Olivia, MN 56277
Office: 320-523-3759 - Fax: 320-523-3755
www.renvillecountymn.com

Parcel Number	Landowner	Created Date
11-00620-00	Brouwer/Arvin & Eileen	2025-05-14



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Repair Report - 2025

Drainage System: Judicial Ditch 1 RC

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						


Requested Repairs (Lines)









Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
Final Repair Cost						

Total Ditch Repair Cost: \$0.00



Repair Status			
	Awaiting		Buffer Noncompliances
	Closed		Noxious Weed Blights
	Invoiced		Tree Maintenance Segments
	Level/Seed		
	Open		



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Inspection Report

Drainage System: Judicial Ditch 7
 Inspection Date: 2025-05-13
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

- District 1:
- District 2:
- District 3:
- District 4:
- District 5: X

Type of Inspection:

- By Foot:
- ATV: X
- Pickup:
- Drone: X

Comments:

Required Repairs

Repair Number	Request Date	Repair Type	Comments	Township	Section
25-026	2025-05-13	Blockage		Ericson	24
25-032	2025-05-13	Washout	Look into stream barb option	Wang	12
25-030	2025-05-13	Washout	Large washout need a long reach	Ericson	8
25-031	2025-05-13	Washout		Ericson	8
25-033	2025-05-13	Washout		Wang	11
25-029	2025-05-13	Blockage	Long reach needed	Ericson	8
25-025	2025-05-13	Blockage	Couple of islands in the channel	Ericson	15
25-027	2025-05-13	Blockage	Long reach needed	Ericson	24
25-028	2025-05-13	Washout		Crooks	7

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch Judicial Ditch 7



Drainage Department

Government Services Center
105 South 5th Street - Suite 319 - Olivia, MN 56277
Office: 320-523-3759 - Fax: 320-523-3755
www.renvillecountymn.com

Noxious Weeds Present

There were no noxious weeds found in Judicial Ditch 7

Trees Present

There were no trees found in Judicial Ditch 7



Drainage System Repair Report - 2025

Drainage System: Judicial Ditch 7

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
25-321	Closed	Crooks	18	Washout	Rock slide down covering his outlet pipe.	\$1,668.28
Final Repair Cost						\$1,668.28

Requested Repairs (Lines)


Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
20-168	Closed	Wang	9	Blockage	Large cottonwood tree in channel	\$550.00
25-026	Open	Ericson	24	Blockage		
25-032	Awaiting	Wang	12	Washout	Look into stream barb option	
25-030	Open	Ericson	8	Washout	Large washout need a long reach	
25-031	Open	Ericson	8	Washout		
25-033	Level/Seed	Wang	11	Washout		\$5,577.23
25-029	Open	Ericson	8	Blockage	Long reach needed	
25-025	Open	Ericson	15	Blockage	Couple of islands in the channel	
25-027	Open	Ericson	24	Blockage	Long reach needed	
25-028	Level/Seed	Crooks	7	Washout		\$7,381.25
Final Repair Cost						\$13,508.48

Total Ditch Repair Cost:

\$15,176.76



Judicial Ditch 7

Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Inspection Report

Drainage System: Judicial Ditch 8
 Inspection Date: 2025-05-09
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot: X
 ATV: X
 Pickup:
 Drone:

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch Judicial Ditch 8

Noxious Weeds Present

There were no noxious weeds found in Judicial Ditch 8

Trees Present

There were no trees found in Judicial Ditch 8



Drainage System Repair Report - 2025

Drainage System: Judicial Ditch 8 RC

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						


Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
25-820	Level/Sealed	Ericson	13	Flow Issue	Ditch Cleanout	21570.64	\$30,920.00
Final Repair Cost							\$30,920.00









Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
2	Closed	Crooks	1	Drop Pipe Needed		\$2,152.25
1	Closed	Ericson	11	Reseed	Level	\$285.25
Final Repair Cost						\$2,437.50

Total Ditch Repair Cost: \$33,357.50



Judicial Ditch 8

Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Inspection Report

Drainage System: Judicial Ditch 16
 Inspection Date: 2025-05-14
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3: X
 District 4:
 District 5: X

Type of Inspection:

By Foot:
 ATV: X
 Pickup:
 Drone: X

Comments:

Required Repairs

Repair Number	Request Date	Repair Type	Comments	Township	Section
25-042	2025-05-14	Bank Slide		Winfield	5
25-041	2025-05-14	Rusted Pipe	Will need larger excavator to reach outlet	Crooks	1
25-036	2025-05-14	Multiple Washouts	Washout each side of the ditch	Crooks	5
25-038	2025-05-14	Bank Slide	Will need large excavator	Crooks	5
25-037	2025-05-14	Washout		Crooks	5
25-039	2025-05-14	Washout		Crooks	5
25-040	2025-05-14	Blockage	Tree in the channel	Crooks	4

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Parcel Number	Landowner	Created Date
09-00700-00	Mulder/Duane M	2025-05-14



Drainage Department

Government Services Center
105 South 5th Street - Suite 319 - Olivia, MN 56277
Office: 320-523-3759 - Fax: 320-523-3755
www.renvillecountymn.com

Noxious Weeds Present

There were no noxious weeds found in Judicial Ditch 16

Trees Present

There were no trees found in Judicial Ditch 16



Drainage System Repair Report - 2025

Drainage System: Judicial Ditch 16

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						

Requested Repairs (Lines)


Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection









Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
20-154.2	Closed	Winfield	6	Fix Crossing	Holes started on both sides	\$7,915.00
20-057	Closed	Crooks	3	Camera Run		
25-042	Level/Seed	Winfield	5	Bank Slide		\$2,370.93
25-036	Level/Seed	Crooks	5	Washout Multi	Washout each side of the ditch	
25-038	Level/Seed	Crooks	5	Bank Slide	Will need large excavator	\$3,876.25
25-037	Level/Seed	Crooks	5	Washout		\$3,479.18
25-039	Level/Seed	Crooks	5	Washout		\$5,924.95
Final Repair Cost						\$23,566.31

Total Ditch Repair Cost:

\$23,566.31



Judicial Ditch 16

Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments



Drainage System Inspection Report

Drainage System: Judicial Ditch 21
 Inspection Date: 2025-05-13
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

District 1:
 District 2:
 District 3:
 District 4:
 District 5: X

Type of Inspection:

By Foot: X
 ATV: X
 Pickup:
 Drone:

Comments:

Required Repairs

There were no required repairs found for this inspection.

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch Judicial Ditch 21

Noxious Weeds Present

There were no noxious weeds found in Judicial Ditch 21

Trees Present

There were no trees found in Judicial Ditch 21



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Repair Report - 2025

Drainage System: Judicial Ditch 21

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						

Requested Repairs (Lines)

Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							









Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
Final Repair Cost						

Total Ditch Repair Cost: \$0.00



Judicial Ditch 21

Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Inspection Report

Drainage System: Judicial Ditch 36
 Inspection Date: 2025-05-05
 Next Inspection Date: 2030
 Inspection Completed By: Shane Bruns

Commissioner District(s):

- District 1:
- District 2:
- District 3:
- District 4:
- District 5: X

Type of Inspection:

- By Foot:
- ATV: X
- Pickup:
- Drone: X

Comments: Look into possible cleanout

Required Repairs

Repair Number	Request Date	Repair Type	Comments	Township	Section
25-001	2025-05-05	Blockage	Trees and other debris in the ditch	Wang	30

Completed Repairs

There were no completed repairs found for this inspection.

16.5' Buffer Non Compliance

Buffer compliance was met for ditch Judicial Ditch 36

Noxious Weeds Present

There were no noxious weeds found in Judicial Ditch 36

Trees Present

There were no trees found in Judicial Ditch 36



Drainage Department

Government Services Center
 105 South 5th Street - Suite 319 - Olivia, MN 56277
 Office: 320-523-3759 - Fax: 320-523-3755
 www.renvillecountymn.com

Drainage System Repair Report - 2025

Drainage System: Judicial Ditch 36

Requested Repairs (Points)

Repair #	Status	Township	Sec	Repair Type	Comments	Repair Cost
Final Repair Cost						


Requested Repairs (Lines)









Repair #	Status	Township	Sec.	Repair Type	Comments	Length	Repair Cost
Final Repair Cost							

Repairs Collected During Inspection

Repair #	Status	Township	Sec.	Repair Type	Comments	Repair Cost
Final Repair Cost						

Total Ditch Repair Cost: \$0.00



Repair Status	
	Awaiting
	Closed
	Invoiced
	Level/Seed
	Open
	Buffer Noncompliances
	Noxious Weed Blights
	Tree Maintenance Segments